



Call Todd Huvad

919.553.5235

[todd@aircraftmerchants.com](mailto:todd@aircraftmerchants.com)

[www.aircraftmerchants.com](http://www.aircraftmerchants.com)

PO Box 1089 • Clayton, NC 27528

## 1946 Ercoupe 415C

### AIRCRAFT SPECIFICATIONS

**N-Number:** N2674H **S/N:** 3299

**Make Offer \$ 47,500**

Sparkling like a diamond in the sunlight, there's no more joyous flying than tooling around in a Ercoupe. This one has been fully re-furbished with excellent upgrades. Features low-time C85 engine, ADS-B, hi-viz Max-Pulse light system. Safety and ops improvements. Always a delight, simple to fly. Summer ev same!

**Airframe:** 1,550 Hours

**Engine:** 40 Hours SMOH

#### Avionics

Garmin Aera 660 GPS  
 - AirGizo Panel Mount  
 - Ships's Power with Circuit Breaker  
 uAvionix AV-30 Primary Flight Digital Display  
 - 3 inch display  
 - Primary Attitude  
 - Primary Direction Indication  
 - Probeless Angle of Attack  
 uAvionix tailBeaconX  
 Transponder  
 - 1090/ESADS-B  
 Apollo GX60 GPS/Comm  
 - Intercom  
 Dual USB Chargeport  
 Steve's Gascolator

#### Features

LED Landing Lights  
 Max-Pulse Wig-Wag flashing controller  
 Rebuilt Brakes  
 Belly Strobe  
 Aircraft Refurb Items Include:  
 - New Seat Belts  
 - New Shoulder Harnesses  
 - New Hoses  
 - New Fuel Drains  
 - New Tires  
 - New wing bolts  
 - New elevator cables  
 - New aileron hardware  
 - New electric fuel pump STC (replaces mechanical engine-driven fuel pump)  
 - New fuel level sight gauges on wings and header tanks  
 Auto Fuel STC

#### Interior

Black Vinyl Seating  
 Canvas Luggage Sling  
 Hooker Shoulder Harnesses

#### Exterior

#### Details

MTOW: 1,320 lbs, LSA conformity  
 Engine:  
 Continental C85

Polished Aluminum

Metalized Wings

s/n:

- Spin on oil filter STC

History:

12/2020 - Aircraft made a forced landing due to fuel pump failure to a roadway at South Boston, VA. The right wing was c while taxing. A replacement wing and aileron was installed on the aircraft during the refurbishment project. No other airfra report with records. A new electric fuel pump was installed to replaced the older style engine-driven pump.

Repair entries and 337

- Replaced right wing and aileron

**Located at KHNZ** ([KHNZ Details](#))

Hangared All logs and Records

Call Todd Huvad

919.553.5235

[todd@aircraftmerchants.com](mailto:todd@aircraftmerchants.com)

[www.aircraftmerchants.com](http://www.aircraftmerchants.com)



[See all Pictures and Details at www.aircraftmerchants.com](http://www.aircraftmerchants.com)