

Call Todd Huvard 919.553.5235 todd@aircraftmerchants.com www.aircraftmerchants.com PO Box 1089 • Clayton, NC 27528

1967 Beechcraft V35 Bonanza AIRCRAFT SPECIFICATIONS N-Number: N523Q S/N: D-8582

Remarkably, this sweet V35 has been owned by a single dedicated owner since being used as the Beech factory demonstrator in 1967. Recent upgrades include fresh leather interior and a full Garmin panel including GNS 530 WAAS, GTX 330 Mode S Transponder and mounted GPSMAP 696 with XM Wx. Flight plan at 165 kts and cruise in real comfort. STCs include GAMIs, Speed Slope windshield, Aileron/Flap Gap Seals, and much more. Must see.

Airframe: 5,116 Hours Engine: 57 Hours PROP: 13 HOURS Since New

Avionics	Features
Garmin GNS 530W WAAS IFR/GPS/NAV/COMM	Dual Controls
Garmin GTX-330 Mode S Transponder	- Co-Pilot Yoke PTT
Garmin GMA 340 Audio Panel	Alternate Air
- 4-Place Intercom	Beech 'Magic Hand' Gear Extension System
- Music Input Jack	Hartzell Top Prop 3-blade STC
Garmin GNC-225 NAV/COMM	D'Shannon engine baffles STC
Garmin GPSMAP 696 Portable	D'Shannon Aileron and Flap Gap Seals STC
King KCS-55A HSI with Compass Slaving	D'Shannon Fiberglass Air Scoops STC
Brittain B-5C Autopilot	Brackett Air Filter STC
- Wing Leveler	Airwolf Oil-Air Separator STC
- Altitude Hold	Eagle Quick Drains STC
- Heading and Nav Tracking	JPI EDM 700 Engine Monitor STC
Ryan WX-10 Stormscope	Knots2U HID LED Landing Light STC
JPI EDM 700 Digital Engine Monitor	GAMI Injectors STC
Beech Factory Clock	Cleveland Brakes STC
Avionics Master Switch	B&N V-Tail Brace Kit STC
Emergency Avionics Bus Switch	Shadin DigiFlow Fuel Flow Computer STC
Alcor EGT	Wheelen LED Beacon STC
Panel Rim Lighting	Speed Slope Windshield STC
Over Voltage Warning Light	Pilot's Window Courtesy Window STC
Interior Fresh new interior Beautiful chocolate and tan leather seating Chocolate Carpets Excellent condition Exterior Very good paint Overall Vestal White with maroon and navy stripes	Details This aircraft has old damage history dating 1984 for a left main gear partial collapse. Additional damage in 2013 from ground taxi prop strike event. Full repair documentation. Located at KEWN (KEWN Details) Hangared All logs Full damage records available Call Todd Huvard 919.553.5235 todd@aircraftmerchants.com www.aircraftmerchants.com







See all Pictures and Details at www.aircraftmerchants.com